


# Glove Tester

Device for glove integrity testing.



## Dimensions Glove Tester



## Glove Tester

Dimensions in mm

Width	200
Height	290
Depth	120

## Standards

- 01 USB connector
- 02 Display
- 03 Inflatable seal indicator
- 04 Pressurized air inlet
- 05 Pressure glove inlet/outlet
- 06 Inflatable seal
- 07 Inflatable seal inlet/outlet
- 08 Handle



## Operation Readiness

For operation of the equipment the following must be ensured:

- Pressurised air
- Electric power supply

## Display



## Description

The tester measures a drop in pressure over time. If the pressure drops over the assigned limit an alarm is displayed. A recording of the displayed values must be performed manually as a part of prepared protocol.